

This Page Is Inserted by IFW Operations  
and is not a part of the Official Record

## **BEST AVAILABLE IMAGES**

Defective images within this document are accurate representations of the original documents submitted by the applicant.

Defects in the images may include (but are not limited to):

- BLACK BORDERS
- TEXT CUT OFF AT TOP, BOTTOM OR SIDES
- FADED TEXT
- ILLEGIBLE TEXT
- SKEWED/SLANTED IMAGES
- COLORED PHOTOS
- BLACK OR VERY BLACK AND WHITE DARK PHOTOS
- GRAY SCALE DOCUMENTS

**IMAGES ARE BEST AVAILABLE COPY.**

**As rescanning documents *will not* correct images,  
please do not report the images to the  
Image Problem Mailbox.**



INVENTORS: McNeeley et al.  
Serial No: 10/079,268  
TITLE: "Turntable"  
ATTY. DOCKET NO. 29939/30057/US; Page 1 of 13  
Marshall, Gerstein & Borun LLP 312-474-6300






FIG. 1




INVENTORS: McNeeley et al.  
Serial No: 10/079,268  
TITLE: "Turntable"  
ATTY. DOCKET NO. 29939/30057/US; Page 2 of 13  
Marshall, Gerstein & Borun LLP 312-474-6300



**FIG. 2**




INVENTORS: McNeeley et al.  
Serial No: 10/079,268  
TITLE: "Turntable"  
ATTY. DOCKET NO. 29939/30057/US; Page 3 of 13  
Marshall, Gerstein & Borun LLP 312-474-6300



**FIG. 3**



INVENTORS: McNeeley et al.  
Serial No: 10/079,268  
TITLE: "Turntable"  
ATTY. DOCKET NO. 29939/30057/US; Page 4 of 13  
Marshall, Gerstein & Borun LLP 312-474-6300





INVENTORS: McNeeley et al.  
Serial No: 10/079,268  
TITLE: "Turntable"  
ATTY. DOCKET NO. 29939/30057/US; Page 5 of 13  
Marshall, Gerstein & Borun LLP 312-474-6300




FIG. 6




FIG. 8




FIG. 5






FIG. 7



INVENTORS: McNeeley et al.  
Serial No: 10/079,268  
TITLE: "Turntable"  
ATTY. DOCKET NO. 29939/30057/US; Page 6 of 13  
Marshall, Gerstein & Borun LLP 312-474-6300





INVENTORS: McNeeley et al.  
Serial No: 10/079,268  
TITLE: "Turntable"  
ATTY. DOCKET NO. 29939/30057/US; Page 7 of 13  
Marshall, Gerstein & Borun LLP 312-474-6300




FIG. 11




FIG. 12



INVENTORS: McNeeley et al.  
Serial No: 10/079,268  
TITLE: "Turntable"  
ATTY. DOCKET NO. 29939/30057/US; Page 9 of 13  
Marshall, Gerstein & Borun LLP 312-474-6300




FIG. 15





FIG. 13



**INVENTORS:** McNeeley et al.  
**Serial No:** 10/079,268  
**TITLE:** "Turntable"  
**ATTY. DOCKET NO.** 29939/30057/US; **Page 10 of 13**  
**Marshall, Gerstein & Borun LLP** 312-474-6300

**FIG. 14**





INVENTORS: McNeeley et al.  
Serial No: 10/079,268  
TITLE: "Turntable"  
ATTY. DOCKET NO. 29939/30057/US; Page 11 of 13  
Marshall, Gerstein & Borun LLP 312-474-6300





FIG. 16



**FIG. 17**






FIG. 18